

Agenda

- What is ADA
- HB 1181 Requirements
- What Are we evaluating
- Outstanding Issues for the Self Evaluation Report
- Next Steps



ADA is Required be Law

The Americans with Disabilities Act:

- Was enacted in 1990
- Civil rights law that prohibits discrimination against people who have disabilities.
- Title II of ADA requires public services and public transportation accessible to those with disabilities.
- As part of the update and before the ADA Transition plan is completed, a self evaluation report/study is conducted to inventory and map out the county's transportation facilities for deficiencies.



HB 1181 for ADA

- As part of HB 1181, Clark County is required to develop and implement an ADA Transition Plan as part of the climate change initiative and the Comp Plan update.
- The ADA Transition Plan and Self Evaluation Report are intended to achieve the following:
 - Identify physical obstacles that limit the accessibility of facilities to individuals with disabilities;
 - Describe the methods to be used to make the facilities accessible;
 - · Provide a schedule for making the access modifications; and
 - Identify the public officials responsible for implementation of the transition plan.




Self Evaluation Report will Include

- The county is required to perform a self-evaluation of its current facilities, relative to the accessibility requirements of the current ADA accessibility standards.
- Transportation facilities in this report are those that make up the pedestrian access route and pedestrian circulation path in the public right-of-way as defined in Clark County Code 40.350.
- The types of facilities being evaluated in this report will include curb ramps, sidewalks, and traffic control signals. The report will identify barriers to the accessibility of these facilities as defined by the ADA.



Curb Ramp Visual Inspection Results 2020






Curb Ramp Standards for ADA

Curb ramps getting additional review


Visual review was visual only





Known Sidewalk Defects 2020

Sidewalk Defects





Sidewalk Barrier

Vertical sidewalk displacement





Gap in Sidewalk





Encroachments into Pedestrian Access Route (PAR)





ADA Accessible Pushbuttons (APS)

Audible Message "Walk sign is on to cross Main Street"

Locater tone

Volume of locater tone and message goes up and down with traffic volume

Pilot light turns on when button pushed

Arrow oriented to walk direction

Detent to catch stylus



Large sign explains what to do

Ethernet Communications

Vibrates when WALK is on

3-pound button push



Standoff pedestrian pushbutton brackets





Outstanding Issues

ADA Public Rights-of-Way Self-Evaluation Report

- Current Facilities Inventory and Mapping
- GIS Analysis and Priority Mapping
- We are using 2019 data and 2025 recent data
- Public Outreach and Survey

ADA Transition Plan

- Describe the methods to be used to make the facilities accessible
- Provide a schedule for making the access modifications



Draft Schedule





Discussion & Questions

Clark County Public Service Center

1300 Franklin Street • PO Box 5000

Vancouver, WA 98666-5000

